## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.




FIGURE 1

22	22 New LOP Item Use this form to create a new LOP Item.	lem.	
	6-FEB-2003 - 23	E53 👼 2.5	FC - MOSIBILITY - 7-1
	Current Date Qubti, Marwan	Model Brw MFG Line II	. 78
	SANPLE - NEW LOP ITER	Cirginatring Group	Originating Subgroup
-6%			February
			STIMBITHIMETISE
7	Uescription		2 3 4 5 6 7 8
	Medium 50 Priority	BIW Planning   S   CoCMethods & Standards   Help   Responsible Group   31_Responsible Subgroup	ds Help 15 14 15 14 15 15 14 15 15 14 15 15 15 15 15 15 15 15 15 15 15 15 15
Submitted LOP Information	Subinit Reser		

FIGURE 2

Please retain a copy of this information for your racords. The LOP Tracking Number below has been assigned to your LOP submission.

Responsible Group: BIW Planning Responsible Sub Group: CoC Methods & Standards

BIW MFG Line II Oubti, Marwan

Originator: Model:

2/6/2003 10:27:47 AM 2/1/2003


LOP Tracking Number: 6013

Date Submitted:

Due Date:

LOP Description:

SAMPLE - NEW LOP ITEM



Back to LOP Home

Preparation: Activity:

が 4 Resp. Sub Group CoC Methods & Standards Orig. Sub Group -Underbody Due Date
2772003
Originating Group - 4-7
BIW MFG Line II Responsible Group BIW Planning FIGURE 4 Responsible Sub Group: Enter transfer information below for LOP item number:6013 Date Initiated
2/6/2003 10:27:47 AM
Originator — 4 5
Qubti, Marwan Ester the LOP Hers tracking number to transfer Transfer To Responsible Group: 71 { LOP Item Transfer SAMPLE - NEW LOP ITEM Tracking Number 6013 Description Priority Medium Activity 73/




FIGURE 5

Sample – Detail of 1 LOP item

80

4110 E53 High / Closed Priority / Status The LOP approval and assignment procedure needs to E53 be reviewed. New LOP's should be reviewed by a gr... High / Closed Model All air cleaners in Zone 3 of the bodyshop need to be sewiced. We have a tot of problems with them ... 9/30/2002 I can't select the month or the year for the due date 9/30/2002 for this new tiem, nor can I select the month ... Date Originated Resp. Group Orig. Group Date Date Description displayed is limited to 100 Cheractera. For details, please use Search by LOP number aprion. Claessens, PeterSimmons, Timothy 9/30/2002 5/24/2002 6/17/2002 2002/7/17 2002/7/17 Allen, Bill Dawkins, Howard Qubti, Marwan Adama, Herman LOP Admin BIW E53 Facelift LOP Admin BIW Planning LOP Admin Originator Assigned To LOP Admin 5202025 4733 5734/2002 9/25/2002 8

FIGURE 6






FIGURE 7

136




FIGURE 8

| | Add, Modify, Delete Associate Information Use this form to add, modify or delete a user account.

Associate

Only enter fields to be modified, blank fields will be defaulted to original data.

Modified Original

Associate\*

NT Logon

Address Email

F160RE

Reporting

Add, Modify, Delete Associate Account Information.

Administration

Add, Remove Lead Coordinators.

You may access the following administration tools.

Overview LOP users.

Overview Lead Coordinators.





FIGURE 10



11 GURE 11

